Product Bulletin

Product Bulletin	Change to masking of exhaust manifoild
Segment	Industrial, electric power
Engine Platforms	400 Series
Engine Build Lists	Please note- we are not showing build lists since the change applies to all the above engines
Details of Change What is the Change	All 400 Series engines from the Peterborough facility will be shipped with a polymer film over the exhaust manifold flange rather than the plastic bung that has been used previously
Reason for Change Why was the change made?	Alignment to other engine platforms and facilities
OEM Effect What is the effect on Form, Fit or Function?	Please remove the film before installing the engine (same as plastic bung previously)
Impact on Aftermarket	N/A
Availability	Q3 2022
General Comments	For information only, no action required

Current shipping method:



New shipping method:



Perkins®